**CGDI BMW Prog Fireware and Software Update Guide**

**[CGDI Prog BMW MSV80 key programmer](http://www.cgprogcar.com) is able to update firmware and software on the official site: [www.cgprogcar.com](http://www.cgprogcar.com). Below parts incl. CGDI Prog Firmware and software update instruction.**



**Part 1: 5 steps to update CGDI Prog Firmware**

Step 1. Connect CGDI Pro device to the computer, open CGDI software.



Step 2. Click on "Setting" and then "Upgrade the firmware", waiting.

**Firmware** select "Seting", click "Upgrade the firmware" waitting for entering next interface



Step 3. Updating...



**Firmware** is upgrading, please do not optional operation ！！！

Step 4. CGDI programmer firmware update successfully, again click on "Upgrade the firmware".

**Firmware** **After Firmware updated successfully click again"Upgrade the frimware"**



Step 5. Get message reading " The version is already up to date without upgrading". Click on "OK".



**show"The version is already up to date without upgrading"
show:firware updated sucessfully，can be working normally**

Done

**Part 2: 7steps to update CGDI BMW Prog software**
Step 1. Receive message " There is a new version", click on "OK"

Software

show"There is a new version" click OK

Step 2. Click on "Setting", then "Check for updates", waiting until the next dialog box appears.



Software

select"Seting", click"Check for updates"
waitting for entering next interface

Step 3. Checking local file.

<cursor>**Software**



**checking software，pls dont operate！！！**

Step 4. Detects a new file, click "Yes" to update.

**Software**



**finished checking，detects new file，click OK**

Step 5. Downloading file.

**Software**

| file name | Size | progress rate |
|---|---|---|
| A0000001.bin | 55 kb | finished downloading |
| A0000002.bin | 53 kb | finished downloading |
| A0000003_Message... | 474 b | finished downloading |
| A0000003_Message... | 994 b | finished downloading |
| A0000004.bin | 14 kb | finished downloading |
| About.xml | 1 kb | finished downloading |
| Default_ErrorCode_... | 0 kb | Downloaded 0% |
| Default_ErrorCode_... | 0 kb | Downloaded 0% |
| Default_Message_C... | 0 kb | Downloaded 0% |
| Default_Message_E... | 0 kb | Downloaded 0% |
| Default_Status_CN.... | 0 kb | Downloaded 0% |

Downloading file          Stop download

C:\Program Files (x86)\Changguang\CGDI\UserData\MSV80.jpg   31%

**downloading file,pls dont operate！！！**

Step 6. Finish loading software.

**Software**

| file name | Size | progress rate |
|---|---|---|
| Default_ErrorCode_... | 2 kb | finished downloading |
| Default_ErrorCode_... | 4 kb | finished downloading |
| Default_Message_C... | 1 kb | finished downloading |
| Default_Message_E... | 3 kb | finished downloading |
| Default_Status_CN.... | 2 kb | finished downloading |
| Default_Status_EN.... | 5 kb | finished downloading |
| Main.xml | 5 kb | finished downloading |
| cfg.xml | 148 b | finished downloading |
| firmware.bin | 41 kb | finished downloading |
| version.xml | 84 b | finished downloading |

Downloading software          Stop download

2.37 MB                                          43%

**finished loading software，loading software，pls wait!**

Step 7. CGDI programmer software update successfully. Ready to use the newest software.

**Software**

**<span style="color:red">sofware updated successfully，can working normally</span>**



Done.